

TOP SECRET 242247Z

OUT 54308

26 OCT 1964

HFS 25X1

25X1

25X1

Grace (P) 16

25X1

25X1

REF: A. 9991 (MSN 1011-1) (IN 9823)
B. 0067 (MSN 1012-1) (IN 0128)

SUBJECT: PRELIMINARY EVALUATIONS ON MSN 1011-1 AND MSN 1012-1.

A MORE DETAILED ANALYSIS HAS BEEN CONDUCTED BY PERSONNEL FROM

OF THE ANOMALY REPORTED BY THE

TEAM AT 9991, PARA K (1) AND 0067, PARA K (1)
AND K (2). THE CURRENT CONSENSUS OF OPINION IS THAT THE FOGGING
WAS NOT CAUSED BY CORONA DISCHARGE, BUT RATHER BY SOME UNDETERMINED
LIGHT SOURCE. ALTHOUGH THE PRESENCE OF THE FOG IS VERY EVIDENT,
THE AMOUNT OF DEGRADATION IS SLIGHT. IT IS RECOMMENDED THAT
FURTHER ANALYSIS BE CONDUCTED TO DETERMINE THE EXACT SOURCE OF THIS
ANOMALY.

TOP SECRET

/END OF MESSAGE/

TOP SECRET

GROUP
Excluded from 25X1
downgrading and
declassification